Marine Service Technician Practice Test Questions and Answers

1. What is the most common cause of marine engine overheating?

A) Low fuel pressure
B) Blocked raw water intake or faulty water pump
C) Dirty air filter
D) Bad spark plugs

2. Which component prevents raw seawater from entering the exhaust manifold when the engine is off?

A) Raw water strainer
B) Anti-siphon valve
C) Through-hull valve
D) Heat exchanger

3. What should be done first when winterizing a marine engine?

A) Add fuel stabilizer
B) Change the engine oil
C) Flush the cooling system with fresh water
D) Remove the propeller

4. What is the recommended inspection interval for zinc anodes on a boat?

A) Monthly
B) Every 6 months
C) Annually
D) Every 2 years

Answers: 1-B 2-B 3-C 4-B

For More Marine Service Technician Questions and Answers FREE, Marine Service Technician Online Prep Training, Marine Service Technician Exam, Marine Service Technician Study Guide, Marine Service Technician Flashcards, Marine Service Technician Quizzes visit:

Marine Service Technician Practice Test

Practice Test Geeks © All Rights Reserved