

Certified Welder Practice Test Questions and Answers

1. Which welding position is considered the most difficult?

- A) Flat position (1G)
- B) Horizontal position (2G)
- C) Vertical position (3G)
- D) Overhead position (4G)

2. What is the primary safety equipment required for arc welding?

- A) Safety glasses only
- B) Welding helmet, gloves, and protective clothing
- C) Hard hat only
- D) Steel-toed boots only

3. Which welding defect is caused by insufficient penetration?

- A) Porosity
- B) Lack of fusion
- C) Undercut
- D) Spatter

4. What does the term "root pass" refer to in welding?

- A) The final welding pass
- B) The first welding pass that penetrates to the root
- C) A decorative welding technique
- D) A type of welding rod

Answers: 1-D 2-B 3-B 4-B

For More Certified Welder Questions and Answers FREE, Certified Welder Online Prep Training, Certified Welder Exam, Certified Welder Study Guide, Certified Welder Flashcards, Certified Welder Quizzes visit:

Certified Welder Practice Test

Practice Test Geeks © All Rights Reserved