

Construction Practice Test Questions and Answers

1. Causes of dampness

- A) Soil solidification
- B) Paint whitening
- C) Efflorescence
- D) All of the options are incorrect

2. For spans, couple roof is used.

- A) less than 8 m, but 6.5 m
- B) 6 to 6.5 m but not less than
- C) less than 3.5 m
- D) less than 5 m, but 2.5 m

3. Dado is typically offered in _____.

- A) Living rooms
- B) Garage
- C) Bath rooms
- D) Balcony

4. The landing's minimum width should be

- A) A width of stairs that is halved
- B) Equivalent to the stair width
- C) Stair width twice as wide
- D) Equivalent to the stair width

Answers: 1-D 2-C 3-C 4-D

For More Construction Questions and Answers FREE, Construction Online Prep Training, Construction Exam, Construction Study Guide, Construction Flashcards, Construction Quizzes visit:

[Construction Practice Test](#)